

Assembly Instruction

- 1 Unpack the screen. Slide the screen on the worksurface edge (Figure A) and attached using the thumbscrew once in desired location (Figure B).




Figure A

Figure B

Accessory Clamp Mount Screen

Package Contents

Hardware..... Qty
None

Component.....Qty
Screen 1

Tools Required
None

Part # 3330235
Rev. -

Printed in U.S.A
© 2015 Kimball International, Inc.

Proper product installation, in accordance with these instructions, is the responsibility of the installing agent.